



# Current Pricing & Options Listing

## Bellhousings

Bellhousings are available in 7-1/2, 8-1/8 and 8-5/8 depths. When ordering, please specify block and transmission type.

**Steel Bellhousing Only, No Starter Pocket . . . \$660.00**  
Includes bellhousing blank with 3.150 hole and drilling of block pattern. Inspection holes, liner or crossshaft holes are NOT included.

**Steel Bellhousing and Liner, No Starter Pocket . . . \$925.00**  
Same as above plus Liner and Crossshaft Holes. Transmission pattern holes NOT included.

**Steel Bellhousing with Inspection Holes, No Starter Pocket . . . \$1175.00**  
Same as above plus Transmission Pattern Holes, Inspection Hole and Adjuster Slot with Covers.

**6.1 Steel Bellhousing with Inspection Holes and Starter Pocket . . . \$1375.00**  
Complete bellhousing unit includes Block and Transmission Patterns, Liner, Crossshaft Holes, Inspection Hole, Adjuster Slot with Covers, Starter Pocket and Dust Tube (if applicable).

**6.1 Aluminum Bellhousing with Inspection Holes and Starter Pocket . . . \$2075.00**  
Complete bellhousing unit includes Block and Transmission Patterns, Liner, Crossshaft Holes, Inspection Hole, Adjuster Slot with Covers, Starter Pocket and Dust Tube (if applicable).

**6.1 Aluminum Small Diameter Bellhousing with Inspection Holes and Starter Pocket . . . \$2075.00**  
Complete bellhousing unit for 142 tooth and smaller flywheel includes Block and Transmission Patterns, Liner, Crossshaft Holes, Inspection Hole, Adjuster Slot with Covers, Starter Pocket and Dust Tube (if applicable).

**6.2 Steel Bellhousing with Inspection Holes, No Starter Pocket . . . \$1375.00**  
Bellhousing unit includes Block and Transmission Patterns, Liner, Crossshaft Holes, Inspection Hole, Adjuster Slot with Covers and Dust Tube (if applicable). Also includes 3/4" tabs and bushings installed with current SFI 6.2 bolt upgrade.

**6.3 Aluminum Bellhousing with Inspection Holes and Starter Pocket . . . \$2075.00**  
Bellhousing unit includes Block and Transmission Patterns, Liner, Crossshaft Holes, Inspection Hole, Adjuster Slot with Covers, Starter Pocket and Dust Tube (if applicable). Also includes 1/2" tabs and bushings installed with current SFI 6.3 bolt upgrade.

**6.3 Steel Bellhousing with Inspection Holes and Starter Pocket . . . \$1375.00**  
Bellhousing unit includes Block and Transmission Patterns, Liner, Crossshaft Holes, Inspection Hole, Adjuster Slot with Covers, Starter Pocket and Dust Tube (if applicable). Also includes 1/2" tabs and bushings installed with current SFI 6.3 bolt upgrade.

**Steel Import Front Wheel Drive . . . . . \$2500.00**  
Bellhousing unit includes Block and Transmission Patterns and all necessary openings required.

**Steel Small Diameter Import . . . . . \$1900.00**  
Bellhousing unit includes Block and Transmission Patterns, Crossshaft or Fork Opening, Adjuster Slot and Covers. Available in 6-1/2 or 8-1/8 depths.

## Bellhousing Options

**Option 1: Starter Pocket (6.1 & 6.3 only) . . . \$200.00**  
Install starter pocket per customer specifications and modify liner.

**Option 2: Crossshaft Assembly with Computer Pick-Up . . . . . \$595.00**  
Includes crossshaft, candlestick with computer pick-up provision, fork, crossshaft bung and hardware.

**Option 3: Fork Style Throwout Bearing Assembly . . . . . \$625.00**  
Includes throw-out bearing, bearing collar and retainer spring.

**Option 4: Dust Tube . . . . . \$50.00**  
Drill 1-1/2" hole in bellhousing with 2-1/2" long tube welded in place.

## Recertification Options

Recertification Charge (inspection only, no repair time) . . . . . \$75.00

## Components & Misc.

Misc. Additional Labor . . . . . \$60/hr.  
Adjuster Slot with Cover (includes slot) . . . \$150.00  
Liner Only . . . . . \$145.00  
Crossshaft . . . . . \$73.50  
Candlestick with Computer Pick-up . . . . . \$140.00  
Crossshaft Bung . . . . . \$26.00  
1/2" Studs & Nuts . . . . . \$125.13  
3/4" Studs & Nuts . . . . . \$135.20  
Short Bearing Retainer Collar (5600) . . . . . \$63.00  
Medium Bearing Retainer Collar (5620) . . . . \$69.70  
Long Bearing Retainer Collar (5630) . . . . . \$75.90  
Special Order Bearing Retainer (5630SP) . . \$175.00

### Items Billed Extra for Time & Material

Cleaning of bellhousing  
Repair of bad threads  
Unsticking of liner (difficult disassembly)  
Remove & reinstall tabs